

**Factory name:** Dongguan Sphere sports Co.,LTD  
**Site amfori ID:** 156-025174-001

**Report No.:** JSASCN25088341  
**Audit Date:** Oct 20, 2025  
**Page 1 of 6**



Factory gate



Factory name



Production building



GPS



Raw material warehouse



Cutting



Transfer printing



Sewing



Pressing



Trimming and packing



Finished products warehouse



PPE sign



Chemical with secondary containment




Chemical safety label



Eye washing facility



Fire extinguisher in good condition



Fire-fighting facilities



Fire extinguisher



Exit sign and emergency light



Evacuation plan



Fire hydrant test



Fire alarm test



Emergency light test



Electrical box with warning sign



First aid kits



Potable water



Toilets



Suggestion box



amfori BSCI code



Attendance recorder



NC: Sewing machines were not installed with finger protection device



NC: One high sewing machine was not installed with needle protection device.



NC: 10% of the raw materials and finished products in warehouse of factory were placed against the wall.